

205 Main Street Brattleboro, VT 05301

(802) 254-3677 (24 hrs.) (802) 254-7630 (FAX)

October 19, 1993

Steve Betit and Grace Betit The Administrators of the Estate of Joel Betit PO Box 106 Whitingham, VT 05361

RE:

Summary Report for Jacksonville Sunoco

Route 112, Jacksonville, Vermont

Dear Mr. Betit, Ms. Betit:

Please find enclosed our completed report for the above referenced site. A copy is being submitted to Charles Schwer at the State of Vermont Department of Environmental Conservation.

Should you have any questions please feel free to call me at 254-3677.

Sincerely,

TRI-S, Inc._Environmental Consulting

Kirsten H. Jeppesen

Environmental Technician

Enclosure

cc:

Charles Schwer

KHJ/dan

\369\betit.let

Branch Office:

25 Pinney Street, Ellington, CT 06029 (203)875-2110 (24 hrs.)

Fax: (203) 875-8587 (24 hrs.)

Summary Report Jacksonville Sunoco Route 112 Jacksonville, Vermont

for

Steve Betit and Grace Betit
The Administrators of the Estate of Joel Betit
P.O. Box 106
Whitingham, Vermont 05361

prepared by

TRI-S, Inc. Environmental Consulting 205 Main Street Brattleboro, VT 05301

October 19, 1993

Table of Contents

I. Introduction	on
II. Work Per	formed
III. Discussio	on and Conclusions 2
	A. Groundwater Flow System
	B. Groundwater Sampling and Laboratory Results
	C. Soil Contamination
	D. Sensitive Receptors
IV. Recomm	endations5
Appendice	S
Appendix A	Groundwater Potentiometric Map
Appendix B	Monitoring Well Construction Logs
Appendix C	Analytical Laboratory Reports
Appendix D	Isoconcentration Map

I. Introduction

Jacksonville Sunoco is a small gas station/service station located on Route 112 in Jacksonville, Vermont. The station has been closed since June 17th 1991, due to the untimely death of the owner. According to Grace Betit, mother of the former owner and one of the administrators to her son's estate, the underground storage tanks were pumped out soon after the station was closed. Upon the request of Jeanette Felton, sister to the former owner, and the joint administrators of the estate (Grace Betit and Steve Betit), TRI-S, Inc. Environmental Consulting submitted a site specific work plan to the Sites Management Section (SMS) of the Vermont Department of Environmental Conservation. A letter from Chuck Schwer, Supervisor of the SMS, accepting our work plan was received on August 18, 1993 and site work was scheduled at that time. The purpose of this report is to document the work performed at the Jacksonville site and to determine the possible presence, source, and extent of any onsite contamination due to tank leakage and/or inappropriate waste handling and disposal.

II. Work Performed

On 9/9/93, TRI-S, Inc. Environmental Consulting (TEC) and T&K Drilling installed 3 monitoring wells at the Jacksonville Sunoco site. Soil samples were taken at five foot intervals from each well boring and screened onsite according to State of Vermont headspace analysis protocol with a Thermo Environmental Instruments Model 580B Organic Vapor Meter (OVM) calibrated with isobutylene.

Well locations are shown on the Groundwater Potentiometric Map (Appendix A). Results from OVM headspace analysis on soil samples taken during well installation are shown on the Monitoring Well Construction Logs (Appendix B). On 9/14/93, TEC surveyed the site, measured groundwater levels of each well, then purged and sampled the wells. All samples were sent to Matrix Analytical Laboratory in Hopkinton, MA for analysis. The samples were analyzed by EPA Method 8020 for volatile organic aromatics by gas chromatograph, to detect possible petroleum constituents in the soil and groundwater at the site.

III. Discussion and Conclusions

A. Groundwater Flow System

Groundwater elevations for all monitoring wells were calculated and are presented below in Table I. Depth to groundwater was measured through the use of an electronic water level indicator. All measurements were taken with respect to the top of the PVC of each well.

Table I

Groundwater Potentiometric Chart

Date	JS-1	JS-2	JS-3
Top of PVC	98.46	99.64	98.12
09/14/93	93.46	95.04	93.06
All results measured	in feet from	an arbitrary	datum poin

A groundwater potentiometric map was constructed from these elevations and is included as Appendix A. According to our interpretations of limited data points, groundwater flow within the investigation area is to the south - southeast following the topographic gradient.

B. Groundwater Sampling and Laboratory Results

Groundwater was sampled on 9/14/93. Laboratory results were compiled and are summarized below in Table II. Complete laboratory reports are included as Appendix C.

Table II

Groundwater Sampling Results

Date C	Compound		1 1				
	ompound	JS-1	JS-2	JS-3	Duplicate of JS-3	Trip Blank	H.A.R.G.*
03/30/93	Benzene	ND	ND	2.0	2.0	ND	5.0
	Toluene	ND	12.0	1.0	1.0	1.0	2.420.0
- Y	Ethylbenzene	ND	ND	1.0	1.0	ND	680.0
	Xylene	ND	ND	1.0	1.0	ND	400.0
	MTBE	ND	ND	680.0	750.0	ND	40.0

Groundwater contamination detected from sample analysis consisted of non-detectable levels of all contaminants in well JS-1; 12.0 ug/l toluene in well JS-2; 2 ug/l benzene, 5.0 ug/l BTEX, and 680.0 ug/l MTBE in well JS-3;. QA/QC sample trip blank, contained 1.0 ug/l toluene and non-detectable levels of all other contaminants.

A duplicate sample was taken from well JS-3 and revealed levels of 2.0 ug/l benzene, 5.0 ug/l BTEX, and 750.0 ug/l MTBE. A contaminant isoconcentration map is included in Appendix D. Sources of MTBE contamination in well JS-3 include a possible leak in one of the UST systems on site or from spillage of mishandled waste gasoline stored in the waste oil storage area.

C. Soil Contamination

During monitoring well construction, soil contamination was detected at the site. Soil samples were collected from each well boring and analyzed using headspace screening protocol with an OVM. Headspace analysis readings are recorded on the Monitoring Well Construction Logs (Appendix B). Soil samples taken from well JS-1 recorded peak OVM readings of 1.0 ppm at approximately a 9 foot depth. Well JS-2 soil samples recorded OVM readings of 0.0 ppm. Well JS-3 soil samples screened with the OVM peaked at 174.0 ppm at a depth of 5 to 7 feet.

D. Sensitive Receptors


Sensitive receptors within the site vicinity include the adjacent brook (the East Branch of the North River) and residential properties located down stream of the gas station. The homes in the immediate vicinity of the station, the power company (abutting the station to the south), and the gas station get their drinking water from springs off the slope to the west. This slope is located across Route 112 and is topographically upgradient of the gas station. The Jacksonville Sunoco Station has a concrete slab foundation and no basement.

IV. Recommendations

TEC recommends:

- The removal of the four underground storage tanks that are currently out of service and are relatively old. Some of the tanks contain water and petroleum product that will need to be pumped out before tank removal.
- 2. Another round of confirmatory sampling should be performed prior to determining if additional borings or wells are needed.
- 3. The stream, upgradient and downgradient of the site, should also be sampled and analyzed by EPA Method 8020 for volatile organics to determine if any impacts of the site contaminants to this sensitive receptor exist. No other sensitive receptors appear to be immediately threatened at this time.
- Stained soils should be removed from the former waste oil storage area on the south side of building, stockpiled, and polyencapsulated onsite for sampling and disposal.
- 5. The floor drain in the garage should be sealed along with all other drains that do not connect to the municipal sewer system.
- 6. Upon approval and completion of the above tasks a full report will be compiled containing site data and analytical results as well as a remediation plan for the site, if necessary.

Appendix A



Appendix B

TRI-S, INC. ENVIRONMENTAL CONSULTING SOIL BORING/MONITORING WELL LOG

Project #: 369 Date: 9/9/93 Project Name: Jacksonville Sunoco Location: Jacksonville, VT Driller: T&K TEC Personnel: KHJ Boring/Well #: JS-1 Sheet 1 of 3				unoco			SITE LOCUS RELOCUS Paved Relocus Re	
Depth	0.6		Counts 12-18		Rec.	OVM (ppm)	Soil Characterization	As Built Diagram
0-2	grab	sample				0.0		Road Box Native Backfill of 1'Bentonite of Grade 1
5-7	8 refusal	8 grab - \$0	3 male	11	6"	1.0	brown, coarse - medium sand and coarse gravel	Silica Sand Pack
							brown, fine - coarse sand, some coarse - medium gravel	End of Boring
Drilling Me Total Well Groundwat PVC elevat	Depth: er Depth:	HSA 9' 5.0 98.4	,	<u>narbitr</u>	ary bat	um point	Riser Diameter: 2	2" Length: 5½' " Length: 3' Slot Size: 10 und Elevation: 78.77'

Notes:

- 1. Split spoon soil samples are screened for organic vapors via headspace method using a Thermo Environmental Instruments Inc. Organic Vapor Meter Model 580B.
- 2. ND indicates Non-Detectable contaminant concentrations as read by the OVM.
- 3. Samples are collected using a Split Spoon Sampler unless otherwise indicated.
 - 4. Split Spoon Sampler has a 2" diameter and is driven using a 140 lb. hammer falling 30 inches.
 - 5. HSA = Hollow Stem Auger, AR = Air Rotary

TRI-S, INC. ENVIRONMENTAL CONSULTING SOIL BORING/MONITORING WELL LOG

Project #: 369 Date: 9/9/93 Project Name: Jacksonville Sunoco Location: Jacksonville, VT Driller: T&K							SITE LOCUS	
TEC Personnel: KHJ Boring/Well #: JS-2 Sheet 2 of 3					3		Pared Rt. 112	
Depth	0-6	Blow 6-12	Counts 12-18	18-24	Rec. (in.)	OVM (ppm)	Soil Characterization	As Built Diagram
0-2	grab	sample		:		0.0	unsorted brown coarse - medium sand and	Road Box Native Backfill 3 1' Bentonite 32 Grade I
5-61/4	13	11	80		10"	0.0	coarse gravel	Silica Sand Pack
10-32	34	34	30	27	12"	0.0	unsorted brown coarse - medium sand and coarse - fine gravel	Screen
							end of boring	
Drilling Method: H5A Screen Diameter: 2" Length: 7' Total Well Depth: 10' Groundwater Depth: 4.60' PVC elevation: 99.64! To an arbitrary Datum Point Ground Elevation: 100.0'								

- 1. Split spoon soil samples are screened for organic vapors via headspace method using a Thermo Environmental Instruments Inc. Organic Vapor Meter Model 580B.
- 2. ND indicates Non-Detectable contaminant concentrations as read by the OVM.
- 3. Samples are collected using a Split Spoon Sampler unless otherwise indicated.
- 4. Split Spoon Sampler has a 2" diameter and is driven using a 140 lb. hammer falling 30 inches.
- 5. HSA = Hollow Stem Auger, AR = Air Rotary

TRI-S, INC. ENVIRONMENTAL CONSULTING SOIL BORING/MONITORING WELL LOG

Project #: 369 Date: 9/9/93						. '	SITE LOCUS				
Project 1				посо		P.W. 615-3					
Location: Jacksonville, VT						<u> </u>	• 15-3				
Driller: .							\(\lambda_{\alpha\chi}\)				
TEC Per				. 2 .		Paved Rt. 113					
Boring/V	vell #:	**************************************	Selection Committee Committee	<u> </u>			Ph. 119				
Depth		Blow	Counts		Rec.	QVM	Soil Characterization	As Built Diagram			
Deput	9-6	6-12	12-18	18-24	(IS.)	(ppm)		•			
0-2	дгар	sample		<u> </u>	:	0.0		Road Box-Flush House			
	·							Native Backshil			
							1	y l'Bentonite			
-						 -	unsorted	: 🎮			
5-6	12	18	16	29	14"	174.0	brown coarse - medium sand, some coarse - medium gravel	Grade 1 Silica			
	12	16	10	23	1 24			Sand			
6-7						8.2	coarse - fine sand, linle coarse - medium gravel	Pack			
							brown - gray	'			
					<u> </u>						
· .											
							unsorted	5			
10-12	16	30	35	30	10"	1.0	brown coarse - medium sand, some coarse - medium gravel				
				<u> </u>	· · · · · · · · · · · · · · · · · · ·		some coarse - medium gravei	IAAI			
<u> </u>							1				
							-				
	<u> </u>						-				
ļ				-			- 1				
							·				
]				
							.				
				Ī							
							1 1				
	<u> </u>		<u> </u>				1 '				
			<u> </u>				∥ .				
		 ·					•				
<u> </u>			<u> </u>	<u> </u>	<u> </u>		<u> </u>	OU Longth 7/			
Drilling Me Total Well		HSA 10′					Screen Diameter:	2" Length: 7' Length: 3'			
Groundwate				-				Slot Size: 10			
PVC elevat		48.12		Nea	sured t	o an arbitrary	Datum Point Grou	nd Elevation: 98.61			

Notes:

- 1. Split spoon soil samples are screened for organic vapors via headspace method using a Thermo Environmental Instruments Inc.

 Organic Vapor Meter Model 580B.
- 2. ND indicates Non-Detectable contaminant concentrations as read by the OVM.
- 3. Samples are collected using a Split Spoon Sampler unless otherwise indicated.
- 4. Split Spoon Sampler has a 2" diameter and is driven using a 140 lb. hammer falling 30 inches.

Appendix C



RECEIVED SEP 2 7 1993

SUMMARY

Report Date:

09/22/93

Account:

TRI-S Environmental Consulting

Address: P.O. Box 1760

Brattleboro, VT 05302

802-254-3677

Project Manager: Project Name: KHJ

Jacksonville Sunoco (369) (9-15-93)

Project No.: 36

sample Information:

Laboratory ID. Client ID.

Laboratory ID. Client ID.

32584961-001 JS-1-91493-369 32584961-002 JS-2-91493-369 32584961-003 JS-3-91493-369 32584961-004 JS-4-91493-369 32584961-005 JS-01-91493-369 32584961-006 QC Report -Water

Reviewed by

Stephen DiMattei

Quality Assurance Officer

Lab Certifications

EPA ID: No. MA059 Massachusetts: No. 313 Maine: Reciprocity

New York: ELAP No. 11116

Connecticut: No. PH 0515 Florida: QA Plan No. 900437G New Hampshire: No. 24190-A,B

Rhode Island: Reciprocity



Matrix Analytical, Inc. 106 South Street Hopkinton, MA 01748 1 800 3-MATRIX

RECEIVED SEP 27 1993

REPORT FINAL

Client Information

Account:

TRI-S Environmental Consulting

Address:

P.O. Box 1760

Brattleboro, VT 05302

Project Name:

Jacksonville Sunoco (369)(9-15-93)

Project Number:

369 кнј

Project Manager:

Sampler Name:

TRI-S Environmental Consult.

Sample Information

Lab ID:

32584961-001

Client ID: Matrix:

JS-1-91493-369 Water

Date Sampled:

09/14/93 14:52

Date Received:

09/15/93 : 0

Date Reported:

Analytical Parameter	Result	Unit	Detection Limit	Method No.	Analyst	Date Analyzed
OLATILE ORGANICS				····		
Benzene	ND	ug/i	1	8020	kp	09/21/93
Chlorobenzene	ND	ug/l	1	8020	kp	09/21/93
1,2-Dichlorobenzene	ND	ug/l	1	8020	kp	09/21/93
1,3-Dichlorobenzene	ND	ug/l	1	8020	kp	09/21/93
1,4-Dichlorobenzene	NID	ug/l	1	8020	kp	09/21/93
Ethylbenzene	ND	ug/l	1	8020	kp	09/21/93
мтве	ND	ug/l	5	8020	kp	09/21/93
Toluene	ND	ug/l	1	8020	kp	09/21/93
Xylene	ND	ug/l	1	8020	kp	09/21/93
Surrogate Studies - Volatiles						
Bromofluorobenzene (602/8020)	97	Percent	1		kp	09/21/93

RECEIVED SEP 2 7 1993



Matrix Analytical, Inc. 106 South Street Hopkinton, MA 01748 1 800 3-MATRIX

FINAL REPORT

Client Information

Account:

TRI-S Environmental Consulting

Address:

P.O. Box 1760

Brattleboro, VT 05302

Project Name:

Jacksonville Sunoco (369)(9-15-93)

Project Number:

369 KHJ

Project Manager:

Sampler Name:

TRI-S Environmental Consult.

Sample Information

Lab ID:

32584961-002

Client ID:

JS-2-91493-369

Matrix:

Water

Date Sampled:

09/14/93 14:45

Date Received:

09/15/93 : 0

Date Reported:

alytical Parameter	Result	Unit	Detection Limit	Method No.	Analyst	Date Analyze
LATILE ORGANICS						
Benzene	ND	ug/I	1	8020	kp	09/20/9
Chlorobenzene	ND	ug/l	1	8020	kp	09/20/9
1,2-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/9
1,3-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/9
1,4-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/9
Ethylbenzene	ND	ug/l	1	8020	kp	09/20/9
MTBE	ND	ug/l	5	8020	kp	09/20/9
Toluene	12	ug/l	1	8020	kp	09/20/9
Xylene	ND	ug/i	1	8020	kp	09/20/9
rogate Studies - Volatiles						
Bromofluorobenzene (602/8020)	92	Percent	1		kp	09/20/9



Matrix Analytical, Inc. 106 South Street Hopkinton, MA 01748 1 800 3-MATRIX

RECEIVED SEP 2 7 1993

FINAL REPORT

Client Information

Account:

TRI-S Environmental Consulting

Address:

P.O. Box 1760

Brattleboro, VT 05302

Project Name:

Jacksonville Sunoco (369)(9-15-93)

Project Number:

369

Project Manager.

КНЈ

Sampler Name:

TRI-S Environmental Consult.

Sample Information

Lab ID:

32584961-003

Client ID: Matrix: JS-3-91493-369 Water Date Sampled:

09/14/93 14:57

Date Received:

09/15/93 : 0

Date Reported:

			Detection	Method		Date
jalytical Parameter	Result	Unit	Limit	No.	Analyst	Apalyze
DLATILE ORGANICS						
Benzene	2	ug/l	1	8020	kp	09/20/93
Chlorobenzene	ND	ug/l	1	8020	kp	09/20/93
1,2-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/93
1,3-Dichlorobenzene	· ND	ug/l	1	8020	kp	09/20/93
1,4-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/93
Ethylbenzene	1	ug/l	1	8020	kp	09/20/93
мтве	680	ug/l	5	8020	kp	09/20/93
Toluene	1	ug/i	1	8020	kp	09/20/93
Xylene	1	ug/l	1	8020	kp	09/20/9
rrogate Studies - Volatiles						
Bromofluorobenzene (602/8020)	99	Percent			kp	09/20/93



Matrix Analytical, Inc. 106 South Street Hopkinton, MA 01748 1800 3-MATRIX

RECEIVED SEP 2 7 1993

REPORT FINAL

Client Information

Account:

TRI-S Environmental Consulting

Address:

P.O. Box 1760

Brattleboro, VT 05302

Project Name:

Jacksonville Sunoco (369)(9-15-93)

Project Number:

369 KHJ

Project Manager.

Sampler Name:

TRI-S Environmental Consult.

Sample Information

Lab ID:

32584961-004

Client ID: Matrix:

JS-4-91493-369

Water

Date Sampled:

09/14/93 15:02

Date Received:

09/15/93 : 0

Date Reported:

Analytical Parameter	Result	Unit	Detection Limit	Method No.	Analyst	Date Analyzed
VOLATILE ORGANICS						
Benzene	2	ug/l	1	8020	kp	09/20/93
Chlorobenzene	ND	ug/i	1	8020	kp	09/20/93
1,2-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/93
1,3-Dichlorobenzene	ND	ug/I	1	8020	kp	09/20/93
1,4-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/93
Ethylbenzene	1	ug/l	1	8020	kp	09/20/93
мтве	750	ug/i	5	8020	kp	09/20/93
Toluene	1	ug/l	1	8020	kp	09/20/93
Xylene	1	ug/l	1	8020	kp	09/20/93
Surrogate Studies - Volatiles						
Bromofluorobenzene (602/8020)	101	Percent			kp	09/20/93



Matrix Analytical, Inc. 106 South Street Hopkinton, MA 01748 1 800 3-MATRIX

RECEIVED SEP 2 7 1993

FINAL REPORT

Client Information

Account:

TRI-S Environmental Consulting

Address:

P.O. Box 1760

Brattleboro, VT 05302

Project Name:

Jacksonville Sunoco (369)(9-15-93)

Project Number:

369

Project Manager.

KHJ

Sampler Name:

TRI-S Environmental Consult.

Sample Information

Lab ID:

32584961-005

Client ID:

JS-01-91493-369

Matrix:

Water

Date Sampled:

09/14/93 12:32

Date Received:

09/15/93 : 0

Date Reported:

		77	Detection	Method No:	Analysi	Date Analyzed
Analytical Parameter	Result	Unit	Limit	NO.	Analyst	Analyzeu
					•	
VOLATILE ORGANICS Benzene	ND	ug/l	1	8020	kp	09/20/93
Chlorobenzene	ND	ug/l	1	8020	kp	09/20/93
1,2-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/93
1,3-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/93
1,4-Dichlorobenzene	ND	ug/l	1	8020	kp	09/20/93
Ethylbenzene	ND	ug/l	1	8020	kp	09/20/93
MTBE	ND	ug/l	5	8020	kp	09/20/93
Toluene	1	ug/l	1	8020	kp	09/20/93
Xylene	ND	ug/l	1	8020	kp	09/20/93
ourrogate Studies - Volatiles					_	
Bromofluorobenzene (602/8020)	90	Percent			kp	09/20/93



Matrix Analytical, Inc. 106 South Street Hopkinton, MA 01748 1800 3-MATRIX

RECEIVED SEP 2 7 1993

FINAL REPORT

Client Information

Account:

TRI-S Environmental Consulting

Address:

P.O. Box 1760

Brattleboro, VT 05302

Project Name:

Jacksonville Sunoco (369)(9-15-93)

Project Number:

369 KHJ

Project Manager.

Sampler Name:

Sample Information

Lab ID:

32584961-006

Client ID:

QC Report -Water

Matrix:

Water

Date Sampled:

09/14/93 :

Date Received:

09/15/93 : 0

Date Reported:

09/22/93

Analytical Parameter	Result Unit Limit No. Analyst Analyzed
Analytical Parameter	

METHOD BLANK - VOLATILES

Method Blank

ND

ug/l

8020/602

METHOD SUMMARIES

Volatile organic analysis is performed using H/P 5995 or 5970 GC/MS, Tekmar purge and trap, and ALS autosampler. Chromatography incorporates packed and megabore columns. Data reduction is performed on RTE 1000 and ChemStation systems. Tuning is based on BFB standards. Procedural guidelines follow EPA 624 or SW846 for all analyses. Aromatic volatiles listed in VOA 8020 are analyzed using GC/MS systems.

METHOD REFERENCES

- 1. Test Methods For Evaluating Solid Waste: Physical Chemical Methods. EPA SW 846. November 1986.
- 2. Methods For Chemical Analysis of Water and Wastes.

EPA 600/4-79-200. Revised March 1983.

3. Standard Methods For Examination of Water and Wastewater, APHA-AWWA-WACF., 16th Edition, 1985.

	Total		0 +	- - .		·	۲,	7	~	7	7			2							 - -
	ANALYSES REQUESTED	COMMENTS		OR	Ĉ.												COMMENTS				PAGE C
		8										 							MATRIX AWALYTICAL, INC. 100 South Street Hopkinton, MA 01748 1 (600) 302-8149		
													 •			DATE	\$ 3/5//6	915/53	MATRIX ANA 10 Hopkint		
								- 1									BECEIVED BY	172 Male 4	Ash arberton		
		KIU	90		0e	08	۲ ۲		2		2 2			10	ONS / NOTES:	0.# /802	RELINDUSTIED BY	Deal in	In Grala		PROJECT PRICE QUOTE NO.:
COMPANY NAME: TRI-S Environmental Consulting	NORTEST P.O. Box 1760 (205 Main Street)	Brattlebora, VT 05302	369	54-3677	/pce	COLLECTION DATE / TIME	9/14/93 2:53	1 2:45	V 2:51	3:02	1232				SPECIAL INSTRUCTIONS / NOTES:	P.O.#		1]5		
			No.:	PHONE 254-36		TYPE	> M-5			7	Λ				= eurface	aampie:					: -
			Ksonville Sunoce	升		CUENT SAMPLE ID	JS1-9443-369	18-2-91493-369	18-3-91493-369	15-4-91493-369.	J5-01-91493-369				W = weter; GW = groundwater; DW = defaking water; SW = surface	water, S # eat; SED = sediment, SL = sludge; DS = drum sample; O = oii; Vi = wipe; X = other (please describe)		9E:D14,7			
			PROJECT NAME: Jac	PROJECT WANAGER: KHS	SAUPLER(S) NAME: K	LAB USE ONLY)									*TYPE; W = water; GN water; S = eofi O = off; Wf = v		NATRIX ARALYTICAL USE DIALY	NOTES:			

Appendix D

